

BrightSign®

OS8.4 NOTES

Version 8.4.14

AU3x5, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 8.4.10

Improvements

- OS-12828: Improved Bluetooth support when using WD104.
- OS-12672: Reverted WS103 WiFi driver to the previous version.

Bug Fixes

- OS-12813: Fixed a crash when updating BP900 firmware.
- OS-12811: Fixed continual reboot that could occur during USB device enumeration.
- OS-12826: Fixed an issue causing file name corruptions during upload.
- OS-12831: Fixed 3840x2160x60p video streams incorrectly playing through a capture path.
- OS-12843: Fixed Node not using platform CA.
- OS-12871: Fixed @brightsign/virtualinput keyboard not functioning as expected.
- OS-12914: Fixed crash during decoding.