BrightSign®

OS8.2 RELEASE NOTES

Version 8.2.75

AU3x5, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 8.2.72

Bug Fixes

- OS-12660: Fixed crash that could occur if the HTML overlay-scrollbar registry setting is active.