BrightSign®

BrightAuthor:connected RELEASE NOTES

Version 1.6.31

Changes Since v1.6.29

Bug Fixes

- BCN-9304: Connector Volume and Zone Volume Set commands should now work as intended.

- BCN-9446: Custom Application URL setup option will no longer clear automatically after entering a URL.