

**BrightSign®**

# OS8.2 RELEASE NOTES

Version 8.2.55.5

AU3x5, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

## Changes Since 8.2.55

### Important Note

- Warning: The data storage system in use by Chromium processes changes when there is a major upgrade to the Chromium version bundled with the BrightSign OS. While updating to a newer version of the OS is generally stable, there are cases where downgrading the OS can cause the data accessed by Chromium to be inaccessible. Other data not in use by Chromium that can be stored on SD, SSD, USB connected and external devices that contain media, systems files and other data do not share this limitation. Please be sure to test your workflow for any OS upgrades or downgrades before deploying to a production environment.

### New Features

- OS-11947: Added ability to override default storage behavior for HTML Widgets.

### Bug Fixes

- OS-11885: HTML virtual keyboards will no longer disappear when attempting to use them.
- OS-11978: HTML local storage now uses the correct scope.
- OS-11888: HTML widgets now report the correct initial network state.