

BrightSign®

OS8.2 RELEASE NOTES

Version 8.2.82

AU3x5, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 8.2.75

Improvements

- OS-12439: Updated Supervisor to v1.2.114
 - BCN-9612: Players no longer respond to REST API commands after the LDWS has been disabled
 - BCN-9679: Fixed packet capture
 - BCN-9548: Improved /v1/diagnostics/network-configuration API
 - BCN-9534: Fixed devices not being displayed under Networked Units after publishing to LFN.
- OS-12286: @brightsign/networkconfiguration now reports metric zero
- OS-11996: Newer versions of Prolific PL2303 are now supported.

Bug Fixes

- OS-11939: Fixed occasional incorrect crashdumps.