BrightSign®

OS8.5.33 RELEASE NOTES

Version 8.5.33

AU3x5, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 8.5.31

This release covers all changes between 8.5.31 and 8.5.33.

Improvements

- OS-13924: Forced redraw if HTML widget is moved
- OS-14000: HTML widget storage quota can now be made large

Bug Fixes

- OS-14166: Fixed non-HWZ video on 4K242, 4K1042, and 4K1142 models
- OS-14238: Fixed simultaneous video playback from multiple HTML widgets