BrightSign®

BrightAuthor Release Notes

Version 5.0.1.2

LS4x5, HDx25, XDx35, XCx55, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 5.0.1.1

Bug Fixes

• BCN-14273, BCN-14270: Fixed a crash/reboot cycle which occurred on Series 4 and earlier players after installing BrightAuthor version 5.0.1.1