

March 24, 2023

BrightSign[®]

BrightAuthor:connected Release Notes

Version 1.10.0

LS4x5, HDx25, XDx35, XCx55, AU335, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

BrightSign, LLC. 983-A University Ave., Los Gatos, CA 95032 | 408-852-9263 | www.brightsign.biz

Changes Since 1.8.3

XD5 presentations created in BrightAuthor:connected version 1.9.0 or earlier will not work in this 1.10.0 version or future versions of BrightAuthor:connected.

Improvements

- BCN-8667: The Control Cloud network can now add users as an Administrator or as a General Manager
- BCN-14183: Removed the Screens tab from the presentation creation UI for all non-multiscreen Series 5 players. This ensures parity with the upscaling behavior on older players.
- BCN-12409: Ensured that when media is replaced, the new media name does not overwrite the state name

Bug Fixes

- BCN-14119: (XD5) Ensured that video can be added to a presentation
- BCN-13972: Ensured that content and device tags on media items can be removed
- BCN-14178: (XD5, XT5, HD5) Ensured that GPIO appears as an option in presentation authoring
- BCN-9445, 8781: Ensured that deleted HTML sites do not persist when creating and saving presentation images, videos or HTML sites

Miscellaneous

- BCN-13487: Fixed the confusing warning message about the minimum OS version